

| | | | PRC/DeSoto | Flamemaster Chemseal | Pro-Seal | Other |
|--|---|--|------------|-------------------------|------------|---------|
| | MIL-S-38249 TYI / AMS3374 TY 4 | Firewall sealant | PR812 | CS1900 | PS700 | |
| | MIL-S-38228 TYII / DMS1819 | Environmental sealant | PR340 | CS2415 | PS895 | |
| | MIL-S-7502 obsolete Replaced by MIL-S-8802 | Integral fuel tank and fuel cells | PR1221B | CS3201 | PS707 | EC1239B |
| | MIL-S-7124 | Aircraft structure polysulfide | PR1221 | CS3201 A&B | PS894A/B | EC1063B |
| | MIL-S-11031B | Sealing compound Class B black | PR383B | CS3202B | PS247B | EC801B |
| | MIL-PRF-81733 & BMS5-95 | Corrosion Inhibitive | | | PS870 A&B | |
| | MIL-S-8802 TYPE II / AMS-S-8802 | Aircraft fuel tank sealant | PR1440 A&B | CS3204 A&B | | |
| | MIL-S-8802F TYPE I DELETED | Aircraft fuel tank sealant | PR1422 A&B | | | |
| | BMS5-44L | Aircraft Fuel Tank Sealant | | | PS890 A&B | |
| | MIL-S-83430 CANCELED | Aircraft fuel tank sealant Higher temp resistance | PR1750 | CS5500 | PS899 | |
| | | Aircraft fuel tank sealant quick repair | PR1435 | CS3204B-1/4 | | |
| | PENDING | Quick repair windshield sealant | PR1829 | CS5447 | | |
| | DPM 5941 HEROUX | Quick repair sealant | | CS3206B-1/6 | PS860B-1/6 | |
| | MIL-S-4383C | Fuel tank sealing topcoat Buna-N type | PR1005L | CS3600 | | |
| | MIL-PRF-8516G | For electric connections and systems | PR1201 | CS3100 | PS727 | |
| | Proposed AMS 3333 | Windshield sealant | PR1425 | CS3247 | | |
| | MIL-S-8784B / AMS3284 | Replaced by CS3330 A&B below | PR1321 A&B | CS3300 A&B | | |
| | MIL-S-8784B / DMS2410 | Access door sealant lead free | PR1428 A&B | CS3330 A&B | | |
| | AMS 3265 / DMS 2013 | Corrosion inhibitive | PR1775 | CS5500ci | | |
| | AMS 3281 | Fuel tank sealant | PR1776 | CS5530/5540 | | |
| | MIL-S-29574TYI / AMS 3277 TYI | Fast cure - flight line repair | PR1826 | CS5306/5310 | | |
| | MIL-S-29574TYII / AMS 3277 TYII | Fast cure - flight line repair | PR1828 | CS5307/5311 | | |